Operating Guide

AK-SM 800A R4.2.4 Change Log

ID	Title
Security Updates	
1542245	Security update - Remove specific command used by Alsense
New features	
1241944	Official support for Danfoss X-Gate over Modbus/IP
1578895	Implement Reset Mechanism for Application upon detection of task timeout
1519889	Implement improved protection against 'system lockups' (SF#16234801)
1599440	Add the ability to send e-mail with attached diagnostic log
989955	Updated board points for type "time off" defrost, to allow proper exceptions to be handled in Alsense [SF: 13291205]
1008061	Investigate root cause for comm loss issue / implement containment
Fixes and Updates	
1483140	Corrected Real Time Clock drifting issue (SF#16217899)
1525233	Add log message for when history truncation happens
1509748	Add additional timeout for NGINX - when loading 800A s/w
1534664	Add Mutex protection, fixes and added MCU logging
1154463	Corrected Schneider IEM3255 does not log history correctly (SF#14154421)
1238562	Corrected DGS (Leak sensor) showing actual reading multiplied by 10 when used in Miscellaneous (SF#14616373)
1308081	G3P write register command not working for 32bit
1328015	Fixed issue with customer specific XML instruction causing resets
1376333	Corrected AK-CC55 Bluetooth lock/unlock fixed (SF# 15832494)
1379049	SM800A DGS Leak Naming Doesn't Transpose correctly on Screen (SF#15538299)
693890	SM800A Local screen - Not possible to set negative values when relative schedules is set for light control (SF#10749457)
757674	Corrected Alsense XML -Lighting Branch reports errors with schedules 7 and 8
1531373	Corrected Number of polls max for Modbus
1557783	Corrected 32-Bit Embedded Writes fails for MCX devices
1573995	Corrected loading old database resets Real Time Clock
1514917	Corrected Alsense XML Issue with reading history configuration